PRODUCT CHANGE NOTICE							
PART NUMBER(S):	PCN No.: 06-0130-48						
Please see attachment.	DATE: January 30, 2006						
PART DESCRIPTION:							
Power Management and Interface Products – Change in Wafer Fabrication Site							
LEVEL OF CHANGE:							
[X] Level I, Customer Approval.	[] Level II, Customer Information.						
PRODUCT ATTRIBUTE AFFECTED:							
 [] Material Change [] Design Change [X] Process Change [X] Other, Explain: Wafer Fabrication 	[] Data Sheet Change [] Package Change [] Packing / Shipping n Site Transfer						
DESCRIPTION OF CHANGE:							
Announcing transfer of certain Power Management and Interface Products from Hillview wafer fabrication facility to wafer foundry Silan. See attached Product List no. 48.							
REASON FOR CHANGE:							
Power Management and Interface products as listed are being transferred to external wafer foundry, due to cessation of operations of the Sipex Hillview Wafer Fabrication manufacturing site.							
FABRICATION PROCESS QUALIFICATION COMPLETED (DATE): May 28, 2006	PRODUCT CHARACTERIZATION COMPLETED AND SAMPLES* AVAILABLE (DATE): May 27, 2006						

^{*} Samples representative of product from the Product Family being transferred.



	PRODUCT CHANGE NOTICE					
EARLIEST DATE OF PRODUC SHIPMENTS: September 23, 2						
EFFECTIVITY CHANGE DATE	OR DATE CODE:	Work week associate	ed wit	th earliest production shipment.		
[] STANDARD DISTRIBUT	ION	1	X]	CUSTOM DISTRIBUTION		
PERSON TO CONTACT WITH	QUESTIONS:					
Fred Claussen						
VP Quality Assurance and Relia Sipex Corporation Phone Number: 408-935-7644 FAX NUMBER: 408-935-7678	ability					



PRODUCT CHANGE NOTICE

PCN No.: 06-0130-48

List 48

	SPX1583T5-3-3	SPX1582U5-L-2-85	SPX1587T-5-0
SPX1582T5-5-0	SPX1583T5-L-3-3	SPX1583T5-2-85	SPX1587T-L-5-0
SPX1582T5-L-5-0	SPX1587U-1-8	SPX1583T5-L-2-85	SPX1587U-5-0
SPX1582U5-5-0	SPX1587U-L-1-8	SPX1583U5-2-85	SPX1587U-L-5-0
SPX1582U5-L-5-0	SPX1582T5-2-5	SPX1583U5-L-2-85	SPX1582T5
SPX1582T5-1-5	SPX1582T5-L-2-5	SPX1587AT-2-85	SPX1582T5-L
SPX1582T5-L-1-5	SPX1582U5-2-5	SPX1587AT-L-2-85	SPX1582U5
SPX1582U5-1-5	SPX1582U5-L-2-5	SPX1587AU-2-85	SPX1582U5-L
SPX1582U5-L-1-5	SPX1583T5-2-5	SPX1587AU-L-2-85	SPX1583T5
SPX1583T5-1-5	SPX1583T5-L-2-5	SPX1587T-2-85	SPX1583T5-L
SPX1583T5-L-1-5	SPX1583U5-2-5	SPX1587T-L-2-85	SPX1583U5
SPX1583U5-1-5	SPX1583U5-L-2-5	SPX1587U-2-85	SPX1583U5-L
SPX1583U5-L-1-5	SPX1587AR-2-5	SPX1587U-L-2-85	SPX1587AR
SPX1587AR-1-5	SPX1587AR-L-2-5	SPX1582T5-3-3	SPX1587AR-L
SPX1587AR-L-1-5	SPX1587AT-2-5	SPX1582T5-L-3-3	SPX1587AT
SPX1587AT-1-5	SPX1587AT-L-2-5	SPX1582U5-3-3	SPX1587AT-L
SPX1587AT-L-1-5	SPX1587AU-2-5	SPX1582U5-L-3-3	SPX1587AU
SPX1587AU-1-5	SPX1587AU-L-2-5	SPX1583U5-3-3	SPX1587AU-L
SPX1587AU-L-1-5	SPX1587R-2-5	SPX1583U5-L-3-3	SPX1587R
SPX1587R-1-5	SPX1587R-L-2-5	SPX1587AR-3-3	SPX1587R-L
SPX1587R-L-1-5	SPX1587T-2-5	SPX1587AR-L-3-3	SPX1587T
SPX1587T-1-5	SPX1587T-L-2-5	SPX1587AT-3-3	SPX1587T-L
SPX1587T-L-1-5	SPX1587U-2-5	SPX1587AT-L-3-3	SPX1587U
SPX1587U-1-5	SPX1587U-L-2-5	SPX1587AU-3-3	SPX1587U-L
SPX1587U-L-1-5	SPX1582T5-2-8	SPX1587AU-L-3-3	
SPX1582T5-1-8	SPX1582T5-L-2-8	SPX1587R-3-3	
SPX1582T5-L-1-8	SPX1582U5-2-8	SPX1587R-L-3-3	
SPX1582U5-1-8	SPX1582U5-L-2-8	SPX1587T-3-3	
SPX1582U5-L-1-8	SPX1583T5-2-8	SPX1587T-L-3-3	
SPX1583T5-1-8	SPX1583T5-L-2-8	SPX1587U-3-3	
SPX1583T5-L-1-8	SPX1583U5-2-8	SPX1587U-L-3-3	
SPX1583U5-1-8	SPX1583U5-L-2-8	SPX1583T5-5-0	
SPX1583U5-L-1-8	SPX1587AT-2-8	SPX1583T5-L-5-0	
SPX1587AR-1-8	SPX1587AT-L-2-8	SPX1583U5-5-0	
SPX1587AR-L-1-8	SPX1587AU-2-8	SPX1583U5-L-5-0	
SPX1587AT-1-8	SPX1587AU-L-2-8	SPX1587AR-5-0	
SPX1587AT-L-1-8	SPX1587T-2-8	SPX1587AR-L-5-0	
SPX1587AU-1-8	SPX1587T-L-2-8	SPX1587AT-5-0	
SPX1587AU-L-1-8	SPX1587U-2-8	SPX1587AT-L-5-0	
SPX1587R-1-8	SPX1587U-L-2-8	SPX1587AU-5-0	
SPX1587R-L-1-8	SPX1582T5-2-85	SPX1587AU-L-5-0	
SPX1587T-1-8	SPX1582T5-L-2-85	SPX1587R-5-0	
SPX1587T-L-1-8	SPX1582U5-2-85	SPX1587R-L-5-0	