PRODUCT CHANGE NOTICE						
PART NUMBER(S):	PCN No.: 06-0130-31					
Please see attachment.	DATE: January 30, 2006					
PART DESCRIPTION:						
Power Management and Interface Products – Change in Wafer Fabrication Site						
LEVEL OF CHANGE:						
[X] Level I, Customer Approval.	[] Level II, Customer Information.					
PRODUCT ATTRIBUTE AFFECTED:						
 [] Material Change [] Design Change [X] Process Change [X] Other, Explain: Wafer Fabrication 	[] Data Sheet Change [] Package Change [] Packing / Shipping n Site Transfer					
DECODIDATION OF CHANCE.						
DESCRIPTION OF CHANGE: Announcing transfer of certain Power Management and Interface Products from Hillview wafer fabrication facility to wafer foundry Silan. See attached Product List no. 31.						
REASON FOR CHANGE:						
Power Management and Interface products as listed are being transferred to external wafer foundry, due to cessation of operations of the Sipex Hillview Wafer Fabrication manufacturing site.						
	PRODUCT CHARACTERIZATION COMPLETED AND SAMPLES* AVAILABLE (DATE): October 29, 2006					

^{*} Samples representative of product from the Product Family being transferred.



€ other	PRODUCT CHANGE NOTICE					
EARLIEST DATE OF PRODU SHIPMENTS: January 27, 20	07					
EFFECTIVITY CHANGE DAT	E OR DATE CODE:	Work week associ	ated wit	h earliest production shipment.		
[] STANDARD DISTRIBU	TION		[X]	CUSTOM DISTRIBUTION		
PERSON TO CONTACT WIT	H QUESTIONS:					
Fred Claussen						
VP Quality Assurance and Re Sipex Corporation Phone Number: 408-935-764- FAX NUMBER: 408-935-7678	4					



PRODUCT CHANGE NOTICE

PCN No.: 06-0130-31

List 31

SP802SXN	SP804REN-L	SP804SXN	SP804TCN-L
SP802SXN-L	SP690SCN	SP804SXN-L	SP804TCP
SP802SXP	SP690SCN-L	SP804SXP	SP804TCP-L
SP802SXP-L	SP690SCP	SP804SXP-L	SP804TEN
SP802TXN	SP690SCP-L	SP804TXN	SP804TEN-L
SP802TXN-L	SP690SEN	SP804TXN-L	SP804TEP
SP802TXP	SP690SEN-L	SP804RXN	SP804TEP-L
SP802TXP-L	SP690SEP	SP804RXN-L	SP805TCN
SP802RXN	SP690SEP-L	SP804RXP	SP805TCN-L
SP802RXN-L	SP802SCN	SP804RXP-L	SP805TCP
SP802RXP	SP802SCN-L	SP804TXP	SP805TCP-L
SP802RXP-L	SP802SEN	SP804TXP-L	SP805TEN
SP690SXN	SP802SEN-L	SP804RCN	SP805TEN-L
SP690SXN-L	SP802SEP	SP804RCN-L	SP805TEP
SP690SXP	SP802SEP-L	SP804RCP	SP805TEP-L
SP690SXP-L	SP690TCN	SP804RCP-L	
SP690TXN	SP690TCN-L	SP804REP	
SP690TXN-L	SP690TCP	SP804REP-L	
SP690TXP	SP690TCP-L	SP805RCN	
SP690TXP-L	SP690TEN	SP805RCN-L	
SP690RXN	SP690TEN-L	SP805RCP	
SP690RXN-L	SP690TEP	SP805RCP-L	
SP690RXP	SP690TEP-L	SP805REN	
SP690RXP-L	SP802TCN	SP805REN-L	
SP802SCP	SP802TCN-L	SP805REP	
SP802SCP-L	SP802TCP	SP805REP-L	
SP690RCN	SP802TCP-L	SP804SCN	
SP690RCN-L	SP802TEN	SP804SCN-L	
SP690RCP	SP802TEN-L	SP804SCP	
SP690RCP-L	SP802TEP	SP804SCP-L	
SP690REN	SP802TEP-L	SP804SEN	
SP690REN-L	SP805RXN	SP804SEN-L	
SP690REP	SP805RXN-L	SP804SEP	
SP690REP-L	SP805RXP	SP804SEP-L	
SP802RCN	SP805RXP-L	SP805SCN	
SP802RCN-L	SP805SXN	SP805SCN-L	
SP802RCP	SP805SXN-L	SP805SCP	
SP802RCP-L	SP805SXP	SP805SCP-L	
SP802REN	SP805SXP-L	SP805SEN	
SP802REN-L	SP805TXN	SP805SEN-L	
SP802REP	SP805TXN-L	SP805SEP	
SP802REP-L	SP805TXP	SP805SEP-L	
SP804REN	SP805TXP-L	SP804TCN	

PROPRIETARY INFORMATION